NWS FORM E-19 (COVER)

U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL WEATHER SERVICE

REPORT ON RIVER GAGE STATION

REVISED, PRINTED DATES: 08/22/2010, 08/22/2010

LOCATION: GLEN ELDER LAKE STREAM: SOLOMON RIVER

BASIN: SOLOMON 12 HSA: GID

REFERENCES:

STATION DESCRIPTION USGS 4/24/1996 USGS STATION DESCRIPTION - 1/31/02

ABBREVIATIONS:

BM - bench mark		EPA - Environmental Protection Agency
DS - downstream		IBWC - International Boundary and Water Comm.
US - upstream	MSRC	- Mississippi River Commission
HW - high water		MORC - Missouri River Commission
LW - low water	NOAA	- National Oceanic and Atmospheric Admin.
RB - right bank		NOS - National Ocean Survey
LB - left bank	NWS	- National Weather Service
MGL - mean gulf level		TVA - Tennessee Valley Authority
MLW - mean low water		USACE - U.S. Army Corps of Engineers
MSL - mean sea level		USBR - U.S. Bureau of Reclamation
MLT - mean low tide		USGS - U.S. Geological Survey
MT - mean tide	USWB	- U.S. Weather Bureau
WQ - water quality		NGVD - National Geodetic Vertical Datum
RM - reference mark		NAD - North American Datum
RP - reference point		

LOCATION IDENTIFICATION: GLNK1 NWS INDEX NUMBER: 14-3100-2 USGS NUMBER: 06874200

MAP OF GAGE LOCATION

LATITUDE: 39 29 46 LONGITUDE: 98 18 48 SOURCE: USGS STN DESCRIPTION

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1 HSA: GID Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 1: GAGE MAP

BENCHMARKS

ELEVATION OF GAGE ZERO: LEVELING AGENCY AND DATE: USGS - 04/24/96 RATING AGENCY: USGS VERTICAL DATUM: NGVD 1929 CHECKBAR: 96.230

BENCHMARK	DESCRIPTION	GAGE ZERO	DATUM
BM1	USBR BRASS CAP "NORTH MASTER BENCH MARK", SOUTH OF THE RESERVOIR OFFICE, ABOUT 30 FT WEST OF PAVED ROAD, PROTECTED BY A METAL FENCE POST.		1502.134
RM1	USGS BRASS CAP SET IN UPSTREAM ABUTMENT, LEFT BANK OF GRANITE CREEK BRIDGE.		1494.874
RM2	CHISLED SQUARE ON LEFT DOWNSTREAM WINGWALL OF RAILROAD BRIDGE AT WIRE WEIGHT LOCATION.		1489.304
RM3	CHISELED SQUARE ON LEFT DOWNSTREAM SIDE (SE CORNER) OF BRIDGE.		1494.868
RM4	CHISELED SQUARE ON RIGHT DOWNSTREAM SIDE (SW CORNER) OF BRIDGE.		1494.972

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1 HSA: GID Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 2: BENCHMARKS

GAGES

DCP TELEM

NESS ID: 346F540A OWNER: USBR REPORT TIME: 0203 INTERVAL: 240 CRITERIA: 1723050A 0136 PAYOR/COST OF LINE: / \$ TYPE OF TELEMETRY: OWNER: PHONE NUMBER: INTERVAL:

1/12/07

GAGE TYPE	OWNER	MAINTENANCE	BEGAN	ENDED	GAGE LOCATION/REMARKS
bubble bubble	USBR USGS	USBR USGS	06/04/1969 04/12/1994	11/01/1999	USGS INSTALLED A WATER-PRESSURE SERVO-MANOMETER GAGE. A SUTRON SHAFT-ENCODER AND SUTRON 8004 DCP INSTALLED
wireweight	USBR	USBR	03/12/1996		4/12/94. GAGE MOUNTED ON THE UPSTREAM BRIDGE RAIL OF THE BRIDGE OVER GRANITE CREEK, WHICH IS ABOUT 3.5 MI WEST ON U.S. 24.

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS ID: GLNK1 HSA: GID

Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 3: GAGES

HISTORY

PUBLICATION/LOCATION (OF RECORDS	STARTING DATE	ENDING DATE
TYPE OF GAGE	OWNER	STARTING DATE	ENDING DATE
bubble	USBR	06/04/1969	11/01/1999
bubble wireweight	USGS USBR	04/12/1994 03/12/1996	
ZERO ELEVATION		STARTING DATE	

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1

Revised, Printed Dates: 08/22/2010, 08/22/2010
NWS FORM E-19 PAGE 4: HISTORY

CRESTS

FLOOD STAGE: ACTION STAGE: FLOOD FLOW: 0 ACTION FLOW: BANKFULL STAGE: 0.00

DATE OF TIME CREST FLOW FROM HIGH BASED ON CAUSED BY
CREST LST (ft) (CFS) WATERMARKS OLD DATUM ICE JAM REMARKS

KE, KS HSA: GID LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1 HSA: GI Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 5: CRESTS

LOW WATER RECORDS

DATE OF STAGE FLOW
LOW WATER (ft) (CFS) REMARKS

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1 HSA: GID Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 6: LOW WATER

CONDITIONS AFFECTING FLOW

MILES ABOVE MOUTH: 172.4 DRAINAGE AREA: 5076.0 POOL STAGE: 1428.0

STREAM BED: RESERVOIR

REACH:

REGULATION: THE DAM IS A ROLLED EARTH-FILL STRUCTURE 15,725 FT IN LENGTH WITH A MAXIMUM HEIGHT OF 115 FT ABOVE THE STREAMBED. THE UPSTREAM SIDE IS FACED WITH SOIL CEMENT. SPILLWAY LOCATED AT THE SOUTH END OF THE STRUCTURE, CONSISTING OF 12 RADIAL

DIVERSION: NA

WINTER:

TOPOGRAPHY: ROLLING HILLS LIGHTLY WOODED

REMARKS: OUTLET IS A 12.5 FT TUNNEL WITH A SILL AT 1407.8 FT AND CAN DISCHARGE 4000 CFS AT RESERVOIR ELEVATION 1455.6 FT AND 5200 CFS AT ELEVATION 1488.3

Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 7: CONDITIONS LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS ID: GLNK1

HSA: GID

DAMAGE

STAGE AREAS AFFECTED

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1

Revised, Printed Dates: 08/22/2010, 08/22/2010
NWS FORM E-19 PAGE 8: DAMAGE

REACH: ELEVATION ZERO: nan

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS ID: GLNK1 HSA: GID Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 9: STAFF

CONTACTS

SQ CONTACT/REMARKS PHONE

1 TONI WOOD 785-545-3314

BUREAU OF RECLAMATION EMPLOYEE WILL ANSWER

2 KS USGS 785-628-8918

MAINTENANCE.

LOCATION: SOLOMON RIVER AT GLEN ELDER LAKE, KS
ID: GLNK1 HSA: GID Revised, Printed Dates: 08/22/2010, 08/22/2010 NWS FORM E-19 PAGE 10: CONTACTS